



Features

Parameter	Symbol	Unit	Min	TypA		
		dB	0			
DeAssert DS	DS _D	dB			1	
DS hysteresis		dB	0			

Note 1: Sensitivity for 10G PRBS 2^{7-1} and BER better than or equal to 10^{-12}

